

BIL	Quotation Reference	Description	Advertisement Date	Closing Date (Not Later Than 09.00AM)	Quotation Fee	Requesting Department	Focal Person
5	BME/A2K/(1233)/2024/HTD(A19)	TO SERVICE (1) UNIT OF HAMILTION TRANSPORT VENTILATOR, IN ICU 3, HOSPITAL RIPAS <u>PLACE OF SUBMISSION:</u> QUOTATION BOX (GROUND FLOOR) MINISTRY OF HEALTH COMMONWEALTH DRIVE BANDAR SERI BEGAWAN, BB 3910 NEGARA BRUNEI DARUSSALAM	20/03/2024	06/04/2024	\$5.00	JABATAN TEKNOLOGI PENJAGAAN KESIHATAN, KEMENTERIAN KESIHATAN.	Muhd Amirul Fazleen Bin Haji Khalidin Jurutera Perubatan Hayat Tel : 2242424 Ext : 8693(RIPASH)

LAMPIRAN - A1

RUJ: BME/A2K/(1233)/2024/HTD (A19)

7/3/2024

TO SERVICE ONE (1) UNIT OF HAMILTION TRANSPORT VENTILATOR , IN ICU 3, HOSPITAL RIPAS.

SCOPE OF WORK

EQUIPMENT DETAILS:

TRANSPORT VENTILATOR, BME14253 , SN: 17756

BRAND: HAMILTION

MODEL: T1

LOCATION: ICU 3, HOSPITAL RIPAS

SCOPE OF WORK

1. To perform Preventive Maintenance work according to manufacturer's guideline (Copy of Manufacturer's guideline/ Checklist for PM must be included)
2. To replace filters and sensors including but not limited to Dust filter, HEPA filter, O2 Inlet filter and O2 sensor.
3. To perform functional and performance test
4. To Perform electrical safety test IEC 60601
5. Perform calibration , verification and testing after replacement of parts.
6. Replacement of Dust filter, HEPA filter, O2 inlet filter, Oxygen sensor & O-ring
7. To ensure software is up to date
8. Provide documentation of all tests performed for user and BME
9. To apply PM done sticker after completion with information such as PM date done and next PM due date.
10. To provide a brief user and technical refresher training

Note*

To use certified analyzer and test equipment

Must be performed trained and certified technician (Certification of technician must be included)

LAMPIRAN - A2

RIJJ: BME/A2K/(1233)/2024/HTD (A19)

TO SERVICE ONE (1) UNIT OF HAMILTION TRANSPORT VENTILATOR , IN ICU 3, HOSPITAL RIPAS.

NO	SPAREPART	PART NUMBER	QUANTITY
1	ONE OFF PLANNED PREVENTIVE MAINTENANCE	SV001	1
2	BATTERY REPLACEMENT	MSP 369108 Hamilton T1	2